456 San Gen DOS	760-550-7739 E. Mison Rd #110 Marcos, CA. 92069 Lic: 1037585 SH# 1190 N 82-2489167			
Insured: Property:	Morongo Valley Fire Department 461 - 11207 Ocotillo Morongo Valley, CA 92256			
Estimator: Company:	Rick Trim High Standards Abatement		Business:	(760) 550-7739
Reference: Company: Business:	High Standards Abatement & Remed 456 E Misson Rd. #110 San Marcos, CA 92069	liation	Business:	(760) 814-2876
Contractor: Company: Business:	High Standards Abatement 456 Misson Road #110 San Marcos , CA 92069			
Claim Number:	Policy Num	ber:	Туре с	of Loss:
Date of Loss: Date Inspected:		Date Received: Date Entered:	8/23/2023 6:18 PM	
Price List: Estimate:	CASD8X_JUL23 Restoration/Service/Remodel MORONGOFD			

EXAMPLATEMENT High Standards Abatement & Remediation

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

Please note the following:

NOTICE / EXCLUSIONS:

Damage to walls and metal structural

connectors, paint, plumbing systems, alarm systems, electronics and electrical systems, and personal property is excluded

and may be unavoidable as a part of the remediation process. We exclude the reinstallation of new materials, fixtures, doors, etc. By accepting this estimate, you acknowledge the above referenced items and will hold High Standards Abatement Inc. or any of it's representatives harmless.

If any plumbing leaks are discovered during the abatement process, additional plumbing charges will apply.

Note: During the first scope of work if there is any additional cleaning or removal, there will be additional cost. This does not include repairs/build back services.

Please note: This estimate does not include the final/post clearance testing services. This is required upon completion of asbestos removal. This service must be done by a third party company. High Standards Abatement Inc. will not perform testing services due to mandatory regulations. Post clearance testing to be coordinated by High Standards Abatement Inc. This does not include complete abatement. Abatement to be performed in areas per estimate.

Note that overlapping damages are present in older homes/building and is unavoidable at certain times. Supplemental abatement will arise for overlapping, additional damages or preexisting damages are found.

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

MORONGOFD

1st Floor

1st Floor

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
1. Respirator - Full face - multi- purpose resp. (per day)	40.00 DA	0.00	7.61	0.00	304.40
2. Respirator cartridge - HEPA only (per pair)	40.00 EA	0.00	15.24	44.20	653.80
3. Add for personal protective equipment - Heavy duty	80.00 EA	0.00	38.87	225.45	3,335.05
4. Plastic bag - used for disposal of contaminated items	700.00 EA	0.00	3.21	162.91	2,409.91
Double bagging of debris per regulation.					
5. Controlled EPA diosposal of hazardous waste	1.50 EA	2,600.00	0.00	0.00	3,900.00
Controlled EPA tracked disposal.					
6. Negative air fan/Air scrubber (24 hr period) - No monit.	16.00 DA	0.00	80.00	0.00	1,280.00
Two for eight days					
7. Equipment decontamination charge - HVY, per piece of equip	2.00 EA	0.00	83.54	0.81	167.89
One air scrubbers.					
8. Peel & seal zipper - heavy duty	4.00 EA	0.00	18.82	3.65	78.93
9. AQMD Notification Fee	1.00 EA	0.00	950.00	0.00	950.00
Total: 1st Floor				437.02	13,079.98

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

	ice				Height: 10'
	568.16 S	F Walls	182.74 SF Ceiling		
	750.90 S	F Walls & Ceiling		32.74 SF Floor	
	20.30 S	Y Flooring	4	57.33 LF Floor Peri	meter
	62.83 L	F Ceil. Perimeter			
6 ' 11" - 1 ' 6"					
Window	1' 7'' X	1' 5''	Opens into Ex	terior	
Window	4' 4'' X	1' 5''	Opens into Ex	terior	
Window	4' X 1'	5''	Opens into Ex	terior	
Door	3' X 6'	7''	Opens into RI	ECEPTION	
Door	2' 6'' X	6' 7''	Opens into H A	ALLWAY	
Window	4' X 1'	5''	Opens into Ex	terior	
Window	3' X 1' 5''		Opens into Exterior		
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
10. Hazardous Waste/Mold Cleaning Technician - per hour	64.00 HR	0.00	93.56	0.00	5,987.84
Certified asbestos technicians to perform	the following:				
Install of two layers 6mil poly sheeting of Removal of asbestos materials - Ceiling drywall/insulation - Vinyl, mastic, and glue down carpet - Hand clean of floors, walls, ceiling - Hepa vacuum of floors, walls, ceiling - Application of asbestos fiberlock encap					
11. Containment Barrier/Airlock/Decon. Chamber - Material Only	1,136.32 SF	0.00	0.16	13.18	194.99
12. Apply asbestos fiber encapsulating compound - Material Only	750.90 SF	0.00	0.50	27.22	402.67
13. Cleaning materials - Rags, sprayers, wire brushes	933.63 SF	0.00	0.01	0.68	10.02
Totals: Office				41.08	6,595.52

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

<u><u><u>12'8"</u></u> <u>2'1"</u> <u>c</u> Rece</u>	ption				Height: 10'
254.91 SF W		SF Walls	7	78.99 SF Ceiling	
tion 4	333.90 SF Walls & Ceiling		78.99 SF Floor		
	8.78	SY Flooring	2	24.00 LF Floor Peri	meter
	36.00	LF Ceil. Perimeter			
⁷ "⊢₄'₄" → 7					
a Door	3' X 6	' 7''	Opens into Ex	terior	
Window	3' X 4	,	Opens into Ex	terior	
Missing Wall - Goes to Floor	3' X 6	' 8''	Opens into CC	PIER_ROOM	
Door	3' X 6	' 7''	Opens into OI	FFICE2	
Missing Wall - Goes to neither Floo	or/Ceiling 4' X 3	' 8''	Opens into RE	CEPTION_4	
Door	3' X 6	' 7''	Opens into RECEPTION_4		
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
14. Hazardous Waste/Mold Cleaning Technician - per hour	32.00 HR	0.00	93.56	0.00	2,993.92
Certified asbestos technicians to perform	the following:				
Install of two layers 6mil poly sheeting or Removal of asbestos materials - Ceiling drywall/insulation - Vinyl, mastic, and glue down carpet - Hand clean of floors, walls, ceiling - Hepa vacuum of floors, walls, ceiling - Application of asbestos fiberlock encaps					
 Containment Barrier/Airlock/Decon. Chamber - Material Only 	509.82 SF	0.00	0.16	5.91	87.48
16. Apply asbestos fiber encapsulating compound - Material Only	333.90 SF	0.00	0.50	12.10	179.05
17. Cleaning materials - Rags, sprayers, wire brushes	412.90 SF	0.00	0.01	0.30	4.43
Totals: Reception				18.31	3,264.88

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

· · · · · · · · · · · · · · · · · · ·	eption 4				Height: 10'
	282.84	SF Walls	72.05 SF Ceiling		
Reception 4	354.88	SF Walls & Ceiling		72.05 SF Floor	
	8.01	SY Flooring		31.67 LF Floor Peri	meter
1'3" 7"	34.67	LF Ceil. Perimeter			
Missing Wall - Goes to neither Floo	or/Ceiling 4' X 3	5' 8''	Opens into RH	CEPTION	
Door	3' X 6	5' 7''	Opens into RH	CEPTION	
Window	5' 7''	X 4'	Opens into Ex	terior	
Window	4' X 1	.' 5''	Opens into Ex	terior	
Window	1' 7''	X 1' 5''	Opens into Ex	terior	
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
18. Hazardous Waste/Mold Cleaning Technician - per hour	32.00 HR	0.00	93.56	0.00	2,993.92
Certified asbestos technicians to perform	the following:				
Install of two layers 6mil poly sheeting of Removal of asbestos materials - Ceiling drywall/insulation - Vinyl, mastic, and glue down carpet - Hand clean of floors, walls, ceiling - Hepa vacuum of floors, walls, ceiling - Application of asbestos fiberlock encap					
 Containment Barrier/Airlock/Decon. Chamber - Material Only 	565.67 SF	0.00	0.16	6.56	97.07
20. Apply asbestos fiber encapsulating compound - Material Only	354.88 SF	0.00	0.50	12.86	190.30
21. Cleaning materials - Rags, sprayers, wire brushes	426.93 SF	0.00	0.01	0.31	4.58
Totals: Reception 4				19.73	3,285.87

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

$\begin{bmatrix} & & & \\ & & & & \\ & & & \\ & & & \\ & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & $	f				Height: 10'
eption 85 24	480.92	SF Walls	201.74 SF Ceiling		
	682.66	SF Walls & Ceiling	20	01.74 SF Floor	
	22.42	SY Flooring	4	51.00 LF Floor Peri	meter
$\begin{bmatrix} 4 & 2 & 4 & 1 \\ 2 & 6 & 2 & 2 \\ -2 & 6 & 2 & 1 \\ -6 & 11 & -4 & -11 & 6 \\ \hline \end{bmatrix}$	58.00	LF Ceil. Perimeter			
Missing Wall - Goes to Floor	4' X 7	" 9"	Opens into FI	LE_ROOM	
Door	3' X 6	7''	Opens into Ex	terior	
Window	4' X 4	.'	Opens into Ex	terior	
Window	4' X 4	.'	Opens into Ex	terior	
Window	4' 1''	X 4'	Opens into Ex	terior	
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
22. Hazardous Waste/Mold Cleaning Technician - per hour	48.00 HR	0.00	93.56	0.00	4,490.88
Certified asbestos technicians to perform	the following:				
Install of two layers 6mil poly sheeting or Removal of asbestos materials - Ceiling drywall/insulation - Vinyl, mastic, and glue down carpet - Hand clean of floors, walls, ceiling - Hepa vacuum of floors, walls, ceiling - Application of asbestos fiberlock encaps					
23. Containment Barrier/Airlock/Decon. Chamber - Material Only	961.83 SF	0.00	0.16	11.16	165.05
24. Apply asbestos fiber encapsulating compound - Material Only	682.66 SF	0.00	0.50	24.75	366.08
25. Cleaning materials - Rags, sprayers, wire brushes	884.40 SF	0.00	0.01	0.64	9.48
Totals: Cheif				36.55	5,031.49

	Copier room	Height: 10'
5 5 5 1 5	303.33 SF Walls	65.31 SF Ceiling
	368.65 SF Walls & Ceiling	65.31 SF Floor
	7.26 SY Flooring	29.33 LF Floor Perimeter
	32.33 LF Ceil. Perimeter	
 Missing Wall - Goes to Floor	3' X 6' 8''	Opens into RECEPTION
MORONGOFD		8/24/2023 Page: 7

Page: 7

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

CONTINUED - Copier room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
26. Hazardous Waste/Mold Cleaning Technician - per hour	16.00 HR	0.00	93.56	0.00	1,496.96
Certified asbestos technicians to perform	the following:				
Install of two layers 6mil poly sheeting or Removal of asbestos materials - Ceiling drywall/insulation - Vinyl, mastic, and glue down carpet - Hand clean of floors, walls, ceiling - Hepa vacuum of floors, walls, ceiling - Application of asbestos fiberlock encaps					
27. Containment Barrier/Airlock/Decon. Chamber - Material Only	606.67 SF	0.00	0.16	7.04	104.11
28. Apply asbestos fiber encapsulating compound - Material Only	368.65 SF	0.00	0.50	13.36	197.69
29. Cleaning materials - Rags, sprayers, wire brushes	433.96 SF	0.00	0.01	0.31	4.65
Totals: Copier room				20.71	1,803.41

y Hallway 4 (File	room				Height: 10'	
	287.54	SF Walls		69.93 SF Ceiling		
	357.47 SF Walls & Ceiling			69.93 SF Floor		
File room	7.77 SY Flooring			27.00 LF Floor Perimeter		
<u></u>	33.50	LF Ceil. Perimeter				
Door	2' 6'' 2	X 6' 7''	Opens into HALLWAY_4			
Missing Wall - Goes to Floor	4' X 7' 9''		Opens into CHEIF			
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
30. Hazardous Waste/Mold Cleaning	16.00 HR	0.00	93.56	0.00	1,496.96	

Technician - per hour

Certified asbestos technicians to perform the following:

Install of two layers 6mil poly sheeting on walls per regulation.

Removal of asbestos materials - Ceiling drywall/insulation

- Vinyl, mastic, and glue down carpet

- Hand clean of floors, walls, ceiling

- Hepa vacuum of floors, walls, ceiling

- Application of asbestos fiberlock encapsulation

MORONGOFD

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

CONTINUED - File room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
31. Containment Barrier/Airlock/Decon. Chamber - Material Only	575.08 SF	0.00	0.16	6.67	98.68
32. Apply asbestos fiber encapsulating compound - Material Only	357.47 SF	0.00	0.50	12.96	191.70
33. Cleaning materials - Rags, sprayers, wire brushes	427.40 SF	0.00	0.01	0.31	4.58

Totals: File room

 5' 2" 	Hallway				Height: 8'	
	268.04	SF Walls	59.65 SF Ceiling			
	327.69	SF Walls & Ceiling		59.65 SF Floor		
1'11" →3'8" → 1 Hallway Hallwa	6.63	SY Flooring	2	32.25 LF Floor Per	imeter	
	39.50	LF Ceil. Perimeter				
Door	2' 6''	X 6' 7''	Opens into OF	FFICE2		
Door	2' X (5' 7''	Opens into Ex	terior		
I11 5" I-2014 11 11" I	Subroom: Hallway 4	(1)			Height: 10'	
	94.51	94.51 SF Walls		5.71 SF Ceiling		
$\begin{bmatrix} 1 & 0 \\ 0 \\ 0 \end{bmatrix}$ Hallway 4 (1)	110.22	SF Walls & Ceiling	15.71 SF Floor			
	1.75	1.75 SY Flooring		6.00 LF Floor Perimeter		
57	16.17	LF Ceil. Perimeter				
Door	2' X (5' 7''	Opens into Ex	terior		
Missing Wall - Goes to Floor	2' 9''	X 6' 8''	Opens into H A	LLWAY		
Door	2' 6''	X 6' 7''	Opens into FILE_ROOM			
Door	2' 11'	2' 11" X 6' 7"		terior		
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
34. Hazardous Waste/Mold Cleani Technician - per hour	ng 64.00 HR	0.00	93.56	0.00	5,987.84	

19.94

1,791.92

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

CONTINUED - Hallway

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Certified asbestos technicians to perform	the following:				
Install of two layers 6mil poly sheeting of Removal of asbestos materials - Ceiling drywall/insulation - Vinyl, mastic, and glue down carpet - Hand clean of floors, walls, ceiling - Hepa vacuum of floors, walls, ceiling - Application of asbestos fiberlock encaps		1.			
35. Containment Barrier/Airlock/Decon. Chamber - Material Only	725.10 SF	0.00	0.16	8.41	124.43
36. Apply asbestos fiber encapsulating compound - Material Only	437.90 SF	0.00	0.50	15.87	234.82
37. Cleaning materials - Rags, sprayers, wire brushes	513.26 SF	0.00	0.01	0.37	5.50
Totals: Hallway				24.65	6,352.59
Total: 1st Floor				617.99	41,205.66
Line Item Totals: MORONGOFD				617.99	41,205.66

Grand Total Areas:


2,540.25	SF Walls	746.12	SF Ceiling	3,286.37	SF Walls and Ceiling
746.12	SF Floor	82.90	SY Flooring	258.58	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	313.00	LF Ceil. Perimeter
746.12	Floor Area	819.65	Total Area	2,626.91	Interior Wall Area
1,121.59	Exterior Wall Area	123.17	Exterior Perimeter of		
			Walls		
0.00	Surface Area	0.00	Number of Course	0.00	Total Darimatar Lanath
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

Summary for Dwelling

Line Item Total	40,587.67
Material Sales Tax	617.99
Replacement Cost Value Net Claim	\$41,205.66 \$41,205.66

Rick Trim



PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

Recap of Taxes

	Material Sales Tax (7.25%)	Storage Rental Tax (7.25%)
Line Items	617.99	0.00
Total	617.99	0.00

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

Recap by Room

Estimate: MORONGOFD


Area: 1st Floor	12,642.96	31.15%
Office	6,554.44	16.15%
Reception	3,246.57	8.00%
Reception 4	3,266.14	8.05%
Cheif	4,994.94	12.31%
Copier room	1,782.70	4.39%
File room	1,771.98	4.37%
Hallway	6,327.94	15.59%
Area Subtotal: 1st Floor	40,587.67	100.00%
Subtotal of Areas	40,587.67	100.00%
Total	40,587.67	100.00%

PH: 760-550-7739 456 E. Mison Rd #110 San Marcos, CA. 92069 Gen Lic: 1037585 DOSH# 1190 FEIN 82-2489167

Recap by Category

Items	Total	%
GENERAL DEMOLITION	3,900.00	9.46%
HAZARDOUS MATERIAL REMEDIATION	36,687.67	89.04%
Subtotal	40,587.67	98.50%
Material Sales Tax	617.99	1.50%
Total	41,205.66	100.00%

1st Floor



[2] 介

1st Floor

Page: 15